

FIG 1
Poor Geometry

SHAFT CAN BE DAMAGED FROM OFF CENTER LOAD




FIG 2
Good Geometry

Mechanical Advantage 2.5 to 1